

DELLA TERRA[®] QUARTZ

by

ARIZONA TILE

www.arizonatile.com

CARE AND MAINTENANCE

CLEANING AFTER FABRICATION

When slab machining is complete, remove any residue from the counter with running water and a clean cloth.

Thoroughly clean the counter with denatured alcohol or acetone to remove excess adhesive, making sure to not allow acetone to set on the surface for any extended period of time.

If, after cleaning, a haze remains on the surface, rinse again. If there are traces of dirt, clean again. The materials containing mother of pearl should not be washed with acidic cleaners.

On smooth surface tops, we do not recommend the application of a surface treatment, such as protective or sealant wax, which over time may cause loss of shine or unevenness in the surface, if not applied correctly

25

CLEANING AFTER INSTALLATION

On completion of installation, thoroughly clean the surface by spraying an acidic or slightly alkaline pH detergent, specific for quartz-resin agglomerates, on the surface, distributing it evenly with a soft sponge.

Leave it for 5 minutes and then rinse with water until the detergent is completely removed. Remove any excess water with a cloth and dry.

The materials containing mother of pearl should not be washed with acidic cleaners.

NOTE: Pay attention to delicate metal parts and other acid-sensitive materials